

Inspection Photos

API: 071-09246

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 5/28/2024

County: LAS ANIMAS



Inspection Photos



Photo 1. Facing southwest along the access road.



Inspection Photos



Photo 2. Facing southwest along the access road.



Inspection Photos



Photo 3. Facing south east along the access road near the location.



Inspection Photos



Photo 4. Facing east at the fill slope. There is an electric utility that remains at the location.



Inspection Photos



Photo 5. Facing east at the location. There are some field bindweed growing in this area that needs to be controlled.



Inspection Photos



Photo 6. Facing northeast at the location. There is less vegetation cover along this area which has not met reference area levels.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09246 | Date: 5/28/2024

Inspection Photos



Photo 7. East side of the location facing west.



Inspection Photos



Photo 8. Facing northwest at the location..



Inspection Photos



Photo 9. Facing south toward the surrounding undisturbed reference vegetation.

