

Inspection Photos  
Location Name: Peanut Federal 3403 PAD  
Location ID: 481827



Photo 1 – LACT Unit



Photo 2 – Tank Battery Signs

**Inspection Photos**  
**Location Name: Peanut Federal 3403 PAD**  
**Location ID: 481827**



**Photo 3 – Separator and ECD**



**Photo 4 – Separators**



**Inspection Photos**  
**Location Name: Peanut Federal 3403 PAD**  
**Location ID: 481827**



**Photo 5 – Compressor**



**Photo 6 – Wellheads**

**Inspection Photos**  
**Location Name: Peanut Federal 3403 PAD**  
**Location ID: 481827**



**Photo 7 – Wellheads – Cellars NOT back filled in**



**Photo 8 – Wellhead and Gas Lift Injection Meter House – Cellars NOT back filled in**



**Inspection Photos**  
**Location Name: Peanut Federal 3403 PAD**  
**Location ID: 481827**



**Photo 9 – Compressors**



**Photo 10 – Instrumental Air Unit**

**Inspection Photos**  
**Location Name: Peanut Federal 3403 PAD**  
**Location ID: 481827**



**Photo 11 – VRUs**



**Photo 12 – ECD**