

Inspection Photos
Location Name: LOUSTALET-65N64W/15NENE
Location #: 330519



Photo #1

Loustalet 41-15 (123-19236) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 5 yds.

Unnecessary Equipment: Wellsite fencing



Photo #2

Loustalet 41-15 Battery site

Abandoned: MOST Equipment Removed

Plugged & Abandoned | PA

Wellsite / Battery entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: LOUSTALET-65N64W/15NENE
Location #: 330519



Colorado Energy & Carbon Management Commission
Weld County
+40.403776, -104.527669
285° W
2024-05-29 12:04

Photo #3

Loustalet 41-15 Battery site

Abandoned: MOST Equipment Removed

Plugged & Abandoned | PA

Unnecessary Equipment: Chemical pump equipment



Colorado Energy & Carbon Management Commission
Weld County
+40.403715, -104.527580
163° S
2024-05-29 12:04

Photo #4

Loustalet 41-15 Battery site

Abandoned: MOST Equipment Removed

Plugged & Abandoned | PA

Unnecessary Equipment: Battery sign

