



Form Resolution To Document Number: 709100266

Razor 22D Photo Documentation

FIRR Doc#: 403807007

Drafted By:



*Melissa Parrish*

Cell: (720)795-3257

Email: [mparrish@fundareresources.com](mailto:mparrish@fundareresources.com)

Production/ Compliance/ Regulatory/ Health & Safety



May 17, 2024 08:39:40  
221 Bronson Avenue  
Raymer  
Weld County  
Colorado

Razor 22D – Wildlife Protection Netting Has Been Restored With Hydrocarbons  
Below Netting At Recycle Pump & Not Accessible To Wildlife



May 17, 2024 08:39:49  
221 Bronson Avenue  
Raymer  
Weld County  
Colorado

Razor 22D – Wildlife Protection Netting Has Been Restored With Hydrocarbons Below Netting At Recycle Pump & Not Accessible To Wildlife



May 17, 2024 08:39:59  
221 Bronson Avenue  
Raymer  
Weld County  
Colorado

Razor 22D – Wildlife Protection Netting Has Been Restored With Hydrocarbons Below Netting At Recycle Pump & Not Accessible To Wildlife



Razor 22D - Tumbleweeds Removed From Around Equipment



Razor 22D - Tumbleweeds Removed From Around Equipment



Razor 22D - Tumbleweeds Removed From Around Equipment



Razor 22D - Tumbleweeds Removed From Around Equipment



Razor 22D - Tumbleweeds Removed From Around Equipment; Hydrocarbons Have Been Cleaned Up & Properly Disposed Of At Wellheads



Razor 22D - Tumbleweeds Removed From Around Equipment; Hydrocarbons Have Been Cleaned Up & Properly Disposed Of At Wellheads



Razor 22D - Tumbleweeds Removed From Around Equipment; Hydrocarbons Have Been Cleaned Up & Properly Disposed Of At Wellheads



Razor 22D - Tumbleweeds Removed From Around Equipment; Hydrocarbons Have Been Cleaned Up & Properly Disposed Of At Wellheads



Razor 22D - Tumbleweeds Removed From Around Equipment; Hydrocarbons Have Been  
Cleaned Up & Properly Disposed Of At Wellheads



Razor 22D - Tumbleweeds Removed From Around Equipment; Hydrocarbons Have Been Cleaned Up & Properly Disposed Of At Wellheads



May 17, 2024 08:51:03  
County Road 116  
Raymer  
Weld County  
Colorado

Razor 22D - Tumbleweeds Removed From Around Equipment; Hydrocarbons  
Have Been Cleaned Up & Properly Disposed Of At Wellheads



Razor 22D - Tumbleweeds Removed From Around Equipment; Hydrocarbons Have Been Cleaned Up & Properly Disposed Of At Wellheads



Razor 22D - Tumbleweeds Removed From Around Equipment; Hydrocarbons Have Been Cleaned Up & Properly Disposed Of At Wellheads



Razor 22D - Tumbleweeds Removed From Around Equipment; Hydrocarbons Have Been Cleaned Up & Properly Disposed Of At Wellheads



Razor 22D - Tumbleweeds Removed From Around Equipment; Hydrocarbons Have Been Cleaned Up & Properly Disposed Of At Wellheads



Razor 22D - Tumbleweeds Removed From Around Equipment; Hydrocarbons Have Been Cleaned Up & Properly Disposed Of At Wellheads



Razor 22D - Tumbleweeds Removed From Around Equipment; Hydrocarbons Have Been Cleaned Up & Properly Disposed Of At Wellheads



Razor 22D - Tumbleweeds Removed From Around Equipment; Hydrocarbons Have Been Cleaned Up & Properly Disposed Of At Wellheads



May 17, 2024 08:58:07  
County Road 116  
Raymer  
Weld County  
Colorado


Razor 22D - Tumbleweeds Removed From Around Equipment; Hydrocarbons Have Been Cleaned Up & Properly Disposed Of At Wellheads



Razor 22D - Tumbleweeds Removed From Around Equipment; Hydrocarbons Have  
Been Cleaned Up & Properly Disposed Of At Wellheads



Razor 22D Unused Equipment Has Been Removed From Within The Bermed Confinement  
Of Methanol Tank



Razor 22D Unused Equipment Has Been Removed From Within The Bermed  
Confinement Of Methanol Tank



May 17, 2024 09:00:47  
County Road 116  
Raymer  
Weld County  
Colorado

Razor 22D Unused Equipment Has Been Removed From Within The Bermed  
Confinement Of Methanol Tank



Razor 22D Unused Equipment Has Been Removed From Within The Bermed  
Confinement Of Methanol Tank



Razor 22D Unused Equipment Has Been Removed From Within The Bermed  
Confinement Of Methanol Tank



Razor 22D Identified during ECMC inspection is a known stormwater collection area. The inspector indicated the area was a release of unknown volume. During the time of inspection, the area contained evaporated stormwater due to precipitation events prior to the inspection.

If necessary to appease ECMC samples can be collected within the area and analyzed for BTEX and TPH.



Razor 22D Identified during ECMC inspection is a known stormwater collection area. The inspector indicated the area was a release of unknown volume. During the time of inspection, the area contained evaporated stormwater due to precipitation events prior to the inspection.

If necessary to appease ECMC samples can be collected within the area and analyzed for BTEX and TPH.



Razor 22D Identified during ECMC inspection is a known stormwater collection area. The inspector indicated the area was a release of unknown volume. During the time of inspection, the area contained evaporated stormwater due to precipitation events prior to the inspection.

If necessary to appease ECMC samples can be collected within the area and analyzed for BTEX and TPH.