





123-09213
DO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT



<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- 123 - 9213		LEASE NAME: FUTURA HORSE #1	
LOCATION: NENE 3 IN 68W		OPERATOR: KPR BASIN	
DATE: 3/10/96		INSPECTOR: SHELTON	
Insp. Type: PR	Insp. Status: PR	PA: Y N	Pass/Fail: (P) F Viol.: Y (N) NOV: Y N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)	OK	
Pits (Reserve/Production) (Rule 902, 903, 904)		
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)		
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)		
Miscellaneous	PUMP JACK INACTIVE AT INSPECTION	

CORRECTIVE ACTION REQUIRED:	 00041532
Date Corrective Action Required By:	Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.