

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 210-20 pad

Location ID: 335342



May 30, 2024 at 1:24:06 PM
CO

Photo # 9037 From entrance to location



May 30, 2024 at 1:25:31 PM
CO

Photo # 9038 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 210-20 pad

Location ID: 335342



Photo # 9039 Improperly marked deadman