

Inspection Photos May 22, 2024
Location Name: Nessu-Kinder 16
Location ID 331124, API 05-123-08713



Wellhead Sign



Wellhead enclosure showing unused equipment outside enclosure.

Inspection Photos May 22, 2024
Location Name: Nessu-Kinder 16
Location ID 331124, API 05-123-08713



Weeds to west of mowed area appear to have spread from site to surrounding land.



Unreadable, non-working pressure gauge.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources