

Inspection Photos  
Location: Apache Canyon 06-09  
Facility ID: 312120  
Remediation # 322832



Photo 1 –Well placard

Photo 2 – Debris and Trash.

**Inspection Photos**  
**Location: Apache Canyon 06-09**  
**Facility ID: 312120**  
**Remediation # 322832**



**Photo 3 – Location looking south, Debris on location**

**Photo 4 – Location looking westerly**

**Inspection Photos**  
**Location: Apache Canyon 06-09**  
**Facility ID: 312120**  
**Remediation # 322832**



**Photo 5 – Rip Rap off fill slope**

**Photo 6 – Fill slope**

Inspection Photos  
Location: Apache Canyon 06-09  
Facility ID: 312120  
Remediation # 322832



**Photo 7 – Spoil pile of material**

**Photo 8 – Access Road through location**

Inspection Photos  
Location: Apache Canyon 06-09  
Facility ID: 312120  
Remediation # 322832



**Photo 9 – Pit Facility ID 292612, fragments of pit liner let around edge of trench.**

**Photo 10 – Pit liner fragments**

**Inspection Photos**  
**Location: Apache Canyon 06-09**  
**Facility ID: 312120**  
**Remediation # 322832**



**Photo 11 – Erosion Rills on cut slope**



**Photo 12 – Pit Spoil pile in southwest corner of location.**