

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403656137
Receive Date:
04/16/2024

Report taken by:
Alexander Ahmadian

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECMC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>CRESTONE PEAK RESOURCES OPERATING LLC</u>	Operator No: <u>10633</u>	Phone Numbers Phone: <u>(303) 2947864</u> Mobile: <u>(303) 8293811</u>
Address: <u>555 17TH STREET SUITE 3700</u>		
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Jacob Evans</u>	Email: <u>jevans@civiresources.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 30404 Initial Form 27 Document #: 403456026

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: _____

SITE INFORMATION

Yes Multiple Facilities

Facility Type: <u>WELL</u>	Facility ID: _____	API #: <u>123-23190</u>	County Name: <u>WELD</u>
Facility Name: <u>ARISTOCRAT ANGUS 2-4-3X</u>		Latitude: <u>40.253950</u>	Longitude: <u>-104.648550</u>
		** correct Lat/Long if needed: Latitude: _____	Longitude: _____
QtrQtr: <u>NWSE</u>	Sec: <u>3</u>	Twp: <u>3N</u>	Range: <u>65W</u> Meridian: <u>6</u> Sensitive Area? <u>No</u>

Facility Type: LOCATION	Facility ID: 305580	API #:	County Name: WELD
Facility Name: ARISTOCRAT ANGUS-63N65W 3NWSE	Latitude: 40.253950	Longitude: -104.648550	
** correct Lat/Long if needed: Latitude:		Longitude:	
QtrQtr: NWSE	Sec: 3	Twp: 3N	Range: 65W Meridian: 6 Sensitive Area? No

Facility Type: SPILL OR RELEASE	Facility ID: 485619	API #:	County Name: WELD
Facility Name: Aristocrat Angus 2-4-3X	Latitude: 40.253950	Longitude: -104.648550	
** correct Lat/Long if needed: Latitude:		Longitude:	
QtrQtr: NWSE	Sec: 3	Twp: 3N	Range: 65W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications SM Most Sensitive Adjacent Land Use Rangeland

Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

The Evans No 2 Ditch is 1120-ft to the SW.
 The Monitoring Well (DWR Receipt 0059507, Permit 59507-MH) approx 225-ft to the NW is the nearest permitted water well. This well was never constructed. The planned construction depth was 20-ft, no static water level recorded. The Monitoring Well (DWR Receipt 3693175B , Permit 314667-) is approx 1175-ft to the NE. This well was constructed to 11-ft, static water level was recorded at 2-ft.
 Groundwater less than 20 ft is not expected at the disturbance location.
 This location is within a HPH Bald Eagle Roost Site. Please see the attached correspondence for the HPH CPW consultation.
 This location is within a 2023 Proposed HPH Mule Deer Severe Winter Range Area. Per NTO from Jan. 4, 2023 titled CPW CONSULTATION PROCESS FOR OPERATIONS IN WILDLIFE HABITATS AT EXISTING OIL AND GAS LOCATIONS, CPW consultation not required.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | |
| <input checked="" type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input checked="" type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	GROUNDWATER	TBD	Laboratory Analytical if Encountered
Yes	SOILS	10' X 10' X 9' bgs	Laboratory Analytical

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

A site investigation will be conducted pursuant to COGCC rule 911 at the ARISTOCRAT ANGUS-63N65W 3NWSE (305580) oil and gas location pertaining to the cut/cap of the ARISTOCRAT ANGUS 2-4-3X (05-123-23190) and abandonment of the ARISTOCRAT ANGUS 2-4-3X (12323190_FL) wellhead line. See site map exhibit for details.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Nine grab confirmation soil samples were collected from the flowline and wellhead excavations. Three composite samples were collected from the stockpile overburden. All samples were analyzed for Table 915-1 organics, TPH C6-36, EC, SAR, pH, and boron. Additionally, at the ECMC reportable wellhead location, Table 915-1 metals were added to the sampling and analysis plan.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

If groundwater is encountered during excavation activities, a grab sample will be collected from the base for laboratory analysis of BTEX, naphthalene, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene, chlorides, sulfates, and TDS.

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil	NA / ND
Number of soil samples collected <u>12</u>	-- Highest concentration of TPH (mg/kg) <u>1631</u>
Number of soil samples exceeding 915-1 <u>6</u>	-- Highest concentration of SAR <u>0.257</u>

Was the areal and vertical extent of soil contamination delineated? No

BTEX > 915-1 No

Approximate areal extent (square feet) 100

Vertical Extent > 915-1 (in feet) 9

Groundwater

Number of groundwater samples collected 0

Highest concentration of Benzene (µg/l) _____

Was extent of groundwater contaminated delineated? No

Highest concentration of Toluene (µg/l) _____

Depth to groundwater (below ground surface, in feet) _____

Highest concentration of Ethylbenzene (µg/l) _____

Number of groundwater monitoring wells installed _____

Highest concentration of Xylene (µg/l) _____

Number of groundwater samples exceeding 915-1 _____

Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected

 Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____

Volume of liquid waste (barrels) _____

Is further site investigation required?

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

The source at the wellhead release location will be removed through mechanical excavation. Impacted soil will be transported under waste manifest to a certified landfill for disposal. Grab soil samples will be collected for laboratory analysis of Table 915-1 metals, organics, TPH C6-36, boron, SAR, EC, and pH.

REMEDICATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Subsequent to source removal, the estimated timeframe to achieve a no further action will be December 31, 2024. The location lies in a HPH-Bald Eagle roost/nest site. Remediation will be postponed until after the nesting/roost season.

Soil Remediation Summary

In Situ

Ex Situ

_____ Bioremediation (or enhanced bioremediation)

_____ Excavate and offsite disposal

_____ Chemical oxidation

_____ If Yes: Estimated Volume (Cubic Yards) _____

_____ Air sparge / Soil vapor extraction

_____ Name of Licensed Disposal Facility or ECMC Facility ID # _____

_____ Natural Attenuation

_____ Excavate and onsite remediation

_____ Other _____

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Air sparge / Soil vapor extraction
_____ Natural Attenuation
_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

Quarterly Semi-Annually Annually Other _____

Request Alternative Reporting Schedule:

Semi-Annually Annually Other _____

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report

Other Decommission Data _____

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

The General Liability coverage within the Civitas Resources insurance program includes coverage for bodily injury, property damage, and pollution clean-up costs arising from qualifying pollution events of a sudden and accidental nature subject to a \$1,000,000 per occurrence limit and \$2,000,000 aggregate limit. The Civitas Resources insurance program includes Excess Liability coverage of \$110,000,000 per occurrence and in the aggregate which sits over the sudden and accidental pollution within the General Liability coverage. It is the opinion of Civitas Resources that this total tower of limit is adequate to address the costs of remediation associated with any qualifying pollution event.

Operator anticipates the remaining cost for this project to be: \$ 80000 _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No _____

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

ECMC Disposal Facility ID #, if applicable: _____

Non-ECMC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No _____

If YES:

Compliant with Rule 913.h.(1).

Compliant with Rule 913.h.(2).

Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? No _____

Does the previous reply indicate consideration of background concentrations? _____

Does Groundwater meet Table 915-1 standards? Yes

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeded program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be in accordance with ECMC 1000 Series Rules.

Is the described reclamation complete? Yes

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim Final

Did the Surface Owner provide the seed mix? No

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? No

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. 09/26/2023

Proposed date of completion of Reclamation. 12/31/2025

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 11/03/2023

Actual Spill or Release date, or date of discovery. 11/02/2023

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 08/06/2023

Proposed site investigation commencement. 08/09/2023

Proposed completion of site investigation. 12/06/2023

REMEDIAL ACTION DATES

Proposed start date of Remediation. 12/07/2023

Proposed date of completion of Remediation. 12/31/2024

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

OPERATOR COMMENT

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Jacob Evans

Title: Environmental Advisor

Submit Date: 04/16/2024

Email: jevans@civiresources.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: Alexander Ahmadian

Date: 06/03/2024

Remediation Project Number: 30404

COA Type**Description**

COA Type	Description
0 COA	

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

403656137	FORM 27-SUPPLEMENTAL-SUBMITTED
403656228	SITE INVESTIGATION REPORT

Total Attach: 2 Files

General Comments**User Group****Comment****Comment Date**

User Group	Comment	Comment Date
		Stamp Upon Approval

Total: 0 comment(s)