

**Inspection Photos**  
**Location: Rock Springs 34-33**  
**Location ID: 309096**



**Photo 1 –Well placard**



**Photo 2 – Wellhead and equipment**

**Inspection Photos**  
**Location: Rock Springs 34-33**  
**Location ID: 309096**



**Photo 3 – Location looking southeast**

**Photo 4 – Location Looking south**



**Inspection Photos**  
**Location: Rock Springs 34-33**  
**Location ID: 309096**



**Photo 5 – Pit Facility ID 301630, Pit Closure in process**



**Photo 6 – Location Looking north to access road**