

Inspection Photos
Location: Patient 42-31
Facility ID: 309098



Photo 1 – Well placard, WDID sticker is not legible

Photo 2 – Unused equipment

Inspection Photos
Location: Patient 42-31
Facility ID: 309098



Photo 3 – Stained soils

Photo 4 – Stained soils

Inspection Photos
Location: Patient 42-31
Facility ID: 309098



Photo 5 – Open ended piping, Signage not properly posted.

Photo 6 – Reclaimed Pit Facility ID 301103

Inspection Photos
Location: Patient 42-31
Facility ID: 309098



Photo 7 – Location Looking east