

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-17 Pad

Location ID: 335248



Photo # 8555 From entrance to location



Photo # 8556 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-17 Pad

Location ID: 335248



Photo # 8557 Location



Photo # 8558 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-17 Pad

Location ID: 335248



Photo # 8559 Location



Photo # 8560 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-17 Pad

Location ID: 335248



Photo # 8561 Location



Photo # 8562 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-17 Pad

Location ID: 335248



Photo # 8563 Debris



Photo # 8564 Open ended load line