

**Operator: CRESTONE PEAK RESOURCES OPERATING LLC**

**Location Name: MANTLE-64N65W 28SWNE**

**Loc ID: 332706**

**Inspection: 714201001**



Exhibit A



Exhibit B



**Exhibit C**

**CA:** Unused equipment at PA wellheads. See attached photos. Comply with Rule 603., Rule 606.

**CA Resolution:** Operator has reported that unused equipment on location has been appropriately removed. Additional actions are being taken regarding the location to review work involving decommission and ensuring the correct documents are in place to make