

Inspection Photos  
Location Name: Caster 8-59-19 PAD  
Location ID: 452871



Energy and Carbon Management Commission  
40.64472, -104.01199, 4922.3ft  
06/03/2024 13:17:19

Photo 1 – 19-24-12 Wellhead



Energy and Carbon Management Commission  
40.64472, -104.01199, 4922.3ft  
06/03/2024 13:17:24

Photo 2 – Well Sign – 24 Hour Contact Number



Inspection Photos  
Location Name: Caster 8-59-19 PAD  
Location ID: 452871




Photo 3 – 19-24-16





Photo 4 – Well Sign – 24 Hour Contact Number




**Inspection Photos**  
**Location Name: Caster 8-59-19 PAD**  
**Location ID: 452871**



**Photo 5 – Wellheads**

**Photo 6 – Well Sign – 24 Hour Contact Number**

**Inspection Photos**  
**Location Name: Caster 8-59-19 PAD**  
**Location ID: 452871**



**Photo 7 – Well Sign – 24 Hour Contact Number**



**Photo 8 – Gas Lift Injection Meter House**



**Inspection Photos**  
**Location Name: Caster 8-59-19 PAD**  
**Location ID: 452871**



**Photo 9 – Separators**



**Photo 10 – Separators**

**Inspection Photos**  
**Location Name: Mottled PAD**  
**Location ID: 453399**



**Photo 11 – Tank Battery Sign**



**Photo 12 – Tank Battery**



**Inspection Photos**  
**Location Name: Mottled PAD**  
**Location ID: 453399**



**Photo 13 – Tank Battery**



**Photo 14 – LACT Unit**

**Inspection Photos**  
**Location Name: Mottled PAD**  
**Location ID: 453399**



**Photo 15 – ECDs**



**Photo 16 – Instrumental Air Unit**



**Inspection Photos**  
**Location Name: Mottled PAD**  
**Location ID: 453399**



**Photo 17 – Compressor**