

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 33-1-795 Pit

Facility ID: 414557



Photo # 9367 From entrance to location



Photo # 9368 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 33-1-795 Pit

Facility ID: 414557



Photo # 9369 Location



Photo # 9370 Location

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC 33-1-795 Pit
Facility ID: 414557



Photo # 9371 Unlabeled chemical drum/contents unknown



Photo # 9372 Unlabeled chemical drum/contents unknown

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 33-1-795 Pit

Facility ID: 414557



Photo # 9373 Open ended piping/wildlife hazard/available for entry by wildlife



Photo # 9374 Open ended piping/wildlife hazard/available for entry by wildlife

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 33-1-795 Pit

Facility ID: 414557



Photo # 9375 Open ended piping/wildlife hazard/available for entry by wildlife



Photo # 9376 Open ended piping/wildlife hazard/available for entry by wildlife

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 33-1-795 Pit

Facility ID: 414557



Photo # 9377 Open ended load line



Photo # 9378 Barbed wire fence around location needs maintenance/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 33-1-795 Pit

Facility ID: 414557



Photo # 9379 Barbed wire fence around location needs maintenance/wildlife hazard



Photo # 9380 Barbed wire fence around location needs maintenance/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 33-1-795 Pit

Facility ID: 414557



Photo # 9381 Barbed wire fence around location needs maintenance/wildlife hazard



Photo # 9382 Barbed wire fence around location needs maintenance/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 33-1-795 Pit

Facility ID: 414557



Photo # 9383 Barbed wire fence around location needs maintenance/wildlife hazard



Photo # 9384 Barbed wire fence around location needs maintenance/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 33-1-795 Pit

Facility ID: 414557



Photo # 9385 Barbed wire fence around location needs maintenance/wildlife hazard



Photo # 9386 Barbed wire fence around location needs maintenance/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 33-1-795 Pit

Facility ID: 414557



Photo # 9387 Barbed wire fence around location needs maintenance/wildlife hazard



Photo # 9388 Barbed wire fence around location needs maintenance/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 33-1-795 Pit

Facility ID: 414557



Photo # 9389 Barbed wire fence around location needs maintenance/wildlife hazard



Photo # 9390 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 33-1-795 Pit

Facility ID: 414557



Photo # 9391 Debris



Photo # 9392 Debris



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 33-1-795 Pit

Facility ID: 414557



Photo # 9393 Debris



Photo # 9394 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC 33-1-795 Pit

Facility ID: 414557



Photo # 9395 Dead weeds/Debris