

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAMOND ELK SR 311-7 Pad

Location ID: 334705



Photo # 9645 From entrance to location



Photo # 9646 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAMOND ELK SR 311-7 Pad

Location ID: 334705



Photo # 9647 Location



Photo # 9648 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAMOND ELK SR 311-7 Pad

Location ID: 334705



Jun 5, 2024 at 12:58:42 PM  
CO

Photo # 9649 Location



Jun 5, 2024 at 12:59:18 PM  
CO

Photo # 9650 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAMOND ELK SR 311-7 Pad

Location ID: 334705



Photo # 9651 Unmarked deadman



Photo # 9652 Same unmarked deadman

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAMOND ELK SR 311-7 Pad

Location ID: 334705



Photo # 9653 Location