

Inspection Photos
Location Name: Linnebur 1
Location ID: 319737



Pic 1 OOSLOT risers are not LOTO



Pic 2 wellhead sign is inadequate. Wrong information.

Inspection Photos
Location Name: Linnebur 1
Location ID: 319737



Pic 3 contaminated soil by wellhead



Pic 4 pump jack motor house / weeds unmanaged

Inspection Photos
Location Name: Linnebur 1
Location ID: 319737



Pic 5 pumpjack motor house / weeds unmanaged



Pic 6 Deadman anchor is not marked