

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 83-1 Pad

Location ID: 334706



Jun 5, 2024 at 1:11:18 PM
CO



Jun 5, 2024 at 1:11:24 PM
CO

Photo # 9675 From entrance to location

Photo # 9676 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 83-1 Pad

Location ID: 334706



Photo # 9677 Location



Photo # 9678 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 83-1 Pad

Location ID: 334706



Photo # 9679 Location



Photo # 9680 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 83-1 Pad

Location ID: 334706



Photo # 9681 Location



Photo # 9682 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 83-1 Pad

Location ID: 334706



Jun 5, 2024 at 1:24:45 PM
CO

Photo # 9683 Location



Jun 5, 2024 at 1:31:40 PM
CO

Photo # 9684 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 83-1 Pad

Location ID: 334706



Photo # 9685 Methanol tank label weathered & cracking /starting to become illegible



Photo # 9686 Capacity on produced water tank label faded /starting to become illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 83-1 Pad

Location ID: 334706




Photo # 9687 Unmarked deadman



Photo # 9688 Same unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 83-1 Pad

Location ID: 334706




Photo # 9689 Unmarked deadman



Photo # 9690 Same unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY RANCH CO GV 83-1 Pad

Location ID: 334706



Photo # 9691 Unmarked deadman