

Inspection Photos

API: 017-07666

Operator: MYSTIQUE RESOURCES COMPAN

Inspection Date: 5/30/2024

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the tank offsite tank battery site. It appears all equipment has been removed. There is a weather station which may not be associated. The crop is planted and is growing.



Inspection Photos



Photo 2. Facing north along the former access road. A sorghum crop has been planted and is growing.



Inspection Photos



Photo 3. Facing north toward the abandoned wellsite. A sorghum crop has been planted and is growing. All equipment has been removed.



Inspection Photos



Photo 4. Facing north at the abandoned wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 5. Facing southeast at the abandoned wellsite.

