

Inspection Photos
Location: Gopher 31-9
Location ID: 309488



Photo 1 –Well placard

Photo 2 – Wellhead and equipment

Inspection Photos
Location: Gopher 31-9
Location ID: 309488



Photo 3 – Tank near Meter House,

Photo 4 – Pit Location

Inspection Photos
Location: Gopher 31-9
Location ID: 309488



Photo 5 – H-brace on truck load out leaning

Photo 6 – Lined pit

Inspection Photos
Location: Gopher 31-9
Location ID: 309488



Photo 7 – Pit fence needs repaired

Photo 8 – Freeboard marker