

Inspection Photos
Location: Graham 22-22 and Graham 22-22 TR
Location ID: 308186



Photo 1 –Well placard, WDID sticker not legible



Photo 2 – TR Well placard

Inspection Photos
Location: Graham 22-22 and Graham 22-22 TR
Location ID: 308186



Photo 3 – KV Wellhead, White stained soils

Photo 4 – TR Wellhead, Packing leak, Notified ENR Foreman

Inspection Photos
Location: Graham 22-22 and Graham 22-22 TR
Location ID: 308186



Photo 5 – Pit ID 270504

Photo 6 – Access road, vehicle rutting

Inspection Photos
Location: Graham 22-22 and Graham 22-22 TR
Location ID: 308186



Photo 7 – Access road, vehicle rutting