



Trujillo - DNR, Aaron <aaron.trujillo@state.co.us>

Follow-up to Inspection Document Number 696205842: Final Reclamation Timeline for the J25 496

1 message

Romana Cowden <RCowden@caerusoilandgas.com>

Fri, Jun 7,

To: "Trujillo - DNR, Aaron" <aaron.trujillo@state.co.us>

Cc: Lindsey Rider <lrider@caerusoilandgas.com>, Brett Middleton <bmiddleton@caerusoilandgas.com>, Kurtis Kissner <kkissner@caerusoilandgas.com>


Good morning Aaron,

Thank you for your time yesterday. With regard to the J25 Frac Pad (Location ID 416051) reclamation corrective action, Caerus is providing the proposed timeline you requested during on 6/6/2024.

The team is in the process of scoping the full decommissioning of the J25 496 support pad, which will include the removal of the remaining surface equipment, pipeline abandonment, remediation, civil recontouring, and seeding. Due to the complex planning process for full abandonment, Form notification requirements and approvals, and wildlife timing stipulations, respectfully requests an extension from the corrective action due date of 7/1/2024 to 11/01/2024.

As discussed, Caerus will be submitting Form 27s for the Facility Closure of the tank battery and associated flowlines. The below timeline reflects NFA approval from the ECMC EPS and a compliance with ECMC Table 915-1.

Caerus proposes the following schedule:



Thank you, and please let me know if you have any questions,

Romana Cowden

EHS Data Analyst

Caerus Oil and Gas LLC

M: 720-951-5895

rcowden@caerusoilandgas.com



Disclaimer

This email message (and any attachments) is for the sole use of the intended recipient(s) and may contain confidential or privileged information. Any unauthorized review, use, disclosure, or distribution you are not the intended recipient, please immediately notify the sender by reply email and destroy all copies of the original message.