

# Inspection Photos

05/30/2024

**Operator:** CAERUS PICEANCE LLC - 10456

**Location ID:** 433573

**Inspection Doc:** 696205848

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 433573



**Photo 1:** Photos 1-2 taken from the east end of the Location. Photo provides an overview of the Location from south, southwest, northwest to north. Location has met ECMC 1004 revegetation requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 433573



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 433573



**Photo 3:** Photos taken from the east end of the Location. Photo example showing patches of Musk thistle establishing on the Location. Weeds in higher densities along the east end of the Location, and more spread out through the central areas of the Location and access road.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 433573



**Photo 4:** Musk thistle patch. Weeds observed within the eastern and central areas of the Location, as well as the access road.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 433573



**Photo 5:** Perimeter fence remaining.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources