

Inspection Photos

May 30th, 2024

Operator: BP America Production Company -
10000

Location ID: 385631

Inspection Document #: 714000805

La Plata County, CO

Township: NWSE 33 35N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Turner Securities 1-33
Location ID: 385631



Photo 1. View of the project area taken from the south west corner facing center.

Inspection Photos

Location Name: Turner Securities 1-33

Location ID: 385631



Inspection Photos
Location Name: Turner Securities 1-33
Location ID: 385631



Inspection Photos
Location Name: Turner Securities 1-33
Location ID: 385631



Inspection Photos
Location Name: Turner Securities 1-33
Location ID: 385631



Photo 5. View of transect #1 within the disturbance area.

Inspection Photos
Location Name: Turner Securities 1-33
Location ID: 385631



5/30/24
+37.255766,-107.748323
183° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. View of the reference area taken from SW corner of the reclamation area facing south. Vegetation comprised of smooth brome and big sage brush.

API #: 067-06506