

# Inspection Photos

May 30th, 2024

Operator: BP America Production Company -  
10000

Location ID: 385860

Inspection Document #: 714000806

La Plata County, CO

Township: NESE 15 35N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos  
Location Name: Pole Barn Monitor Well 1  
Location ID: 385860



**Photo 1.** View of the project area taken from the western edge facing center.



## Inspection Photos

Location Name: Pole Barn Monitor Well 1

Location ID: 385860






## Inspection Photos

Location Name: Pole Barn Monitor Well 1

Location ID: 385860



**Photo 3.** Cardinal photos taken from the center of the disturbance. Left photo facing south, right photo facing west. Note: project area shows minimal desirable vegetation and is dominated by field bindweed and cheatgrass and does not appear consistent with adjacent reference area



Inspection Photos

Location Name: Pole Barn Monitor Well 1

Location ID: 385860



5/30/24

+37.297998,-107.616155

178° S



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** View of the reference area comprised predominantly of smooth brome.

API #: 067-07969