

Inspection Photos

May 30th, 2024

Operator: BP America Production Company -
10000

Location ID: 333610

Inspection Document #: 714000809

La Plata County, CO

Township: NWNW 35 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Briggs A 1
Location ID: 333610

5/30/24
+37.064464,-107.691747
35° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 1. View of the project area taken from the southern edge facing north east.

API #: 067-05000

Inspection Photos
Location Name: Briggs A 1
Location ID: 333610



Inspection Photos
Location Name: Briggs A 1
Location ID: 333610



Photo 3. Cardinal photos taken from the center of the disturbance, left photo facing south, right photo facing west.

Inspection Photos
Location Name: Briggs A 1
Location ID: 333610



Inspection Photos
Location Name: Briggs A 1
Location ID: 333610



Photo 5. Large patch of field bindweed observed within the project area.

Inspection Photos
Location Name: Briggs A 1
Location ID: 333610



Photo 6. View of gully erosion forming in the northern portions of the project area. Additional stabilization is needed.

Inspection Photos
Location Name: Briggs A 1
Location ID: 333610



5/30/24
+37.064994,-107.691419
39° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 7. View of the reference area comprised of smooth brome, juniper and gambel oak.

API #: 067-05000