

Inspection Photos

May 30th, 2024

Operator: BP America Production Company -
10000

Location ID: 325407

Inspection Document #: 714000810

La Plata County, CO

Township: NWNE 8 32N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: WIRT D 1E
Location ID: 325407



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 1. View of the project area taken from the southern edge facing center.

API #: 067-06326

Inspection Photos
Location Name: WIRT D 1E
Location ID: 325407



Inspection Photos
Location Name: WIRT D 1E
Location ID: 325407



Photo 3. Cardinal photos taken from the center of the disturbance, left photo facing south, right photo facing west.

5/30/24
+37.035089,-107.629190
167° S



Inspection Photos
Location Name: WIRT D 1E
Location ID: 325407



Photo 5. Large patch of field bindweed and russian thistle debris observed within the project area.

Inspection Photos
Location Name: WIRT D 1E
Location ID: 325407

5/30/24
+37.034812,-107.627807
359° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Reference are comprised of sage brush and squirrel tail.

API #: 067-06326