

Inspection Photos

May 31st, 2024

Operator: Four Corners Energy LLC - 10754

Location ID: 306964

Inspection Document #: 714000814

La Plata County, CO

Township: SWNE 32 34N 12W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Chevillar 32-32
Location ID: 306964



Photo 1. View of the project area taken from the access point facing center.

Inspection Photos
Location Name: Chevillar 32-32
Location ID: 306964



Photo 2. Cardinal photos taken from the center of the disturbance. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Chevillar 32-32
Location ID: 306964



Photo 3. Cardinal photos taken from the center of the disturbance, left photo facing south, right photo facing west. Note: Disturbance remains unreclaimed.

Inspection Photos
Location Name: Chevillar 32-32
Location ID: 306964



Photo 4. View of fill and cut slopes that remain not recontoured.

Inspection Photos
Location Name: Chevillar 32-32
Location ID: 306964



Photo 5. View of access road that remains unreclaimed.

