

Final Reclamation and Stormwater Inspection

Date: 05/31/2024

Operator: EXTRACTION OIL AND GAS INC - 10459

Location ID: 423393

Inspection Document #: 708201294

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Island Grove Directional 1
Location ID: 423393



Photo 1. Access road does not appear to have been reclaimed with the presence of road base material.

Inspection Photos
Location Name: Island Grove Directional 1
Location ID: 423393



Photo 2. Debris remains on location.

Inspection Photos
Location Name: Island Grove Directional 1
Location ID: 423393



Photo 3. Southwest corner of the location. CO List C Noxious Weeds (Cheatgrass and field bindweed) and undesirable vegetation (kochia) predominate the reclaimed portions.

Inspection Photos
Location Name: Island Grove Directional 1
Location ID: 423393



Photo 4. Southern/middle portion of the location; see comments in Photo 4.

Inspection Photos
Location Name: Island Grove Directional 1
Location ID: 423393



Photo 5. Southeast corner of the location; see comments in Photo 3.

Inspection Photos
Location Name: Island Grove Directional 1
Location ID: 423393



Photo 6. Close up of CO List C Noxious Weed (cheatgrass) that has already gone to seed.

Inspection Photos
Location Name: Island Grove Directional 1
Location ID: 423393



Photo 7. Close up of CO List C Noxious Weed (field bindweed).

Inspection Photos
Location Name: Island Grove Directional 1
Location ID: 423393



Photo 8. Northeast corner of the location; see comments in Photo 3.

Inspection Photos
Location Name: Island Grove Directional 1
Location ID: 423393



Photo 9. Northwest corner of the location; see comments in Photo 3.

Inspection Photos
Location Name: Island Grove Directional 1
Location ID: 423393



Photo 10. Taken near the former tank battery location, facing east; see comments in Photo 3.

Inspection Photos
Location Name: Island Grove Directional 1
Location ID: 423393



Photo 11. Taken near the former tank battery location, facing north; see comments in Photo 3.

Inspection Photos
Location Name: Island Grove Directional 1
Location ID: 423393



Photo 12. Taken near the former tank battery location, facing west; see comments in Photo 3.