

# Inspection Photos

Loc: 307766

Operator: WAPITI OPERATING LLC

Inspection Date: 6/10/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos



**Photo 1.** Facing northeast toward the access road and wellsite.



Inspection Photos



**Photo 2.** Facing southeast toward the wellsite.



## Inspection Photos



**Photo 3.** There is an erosion channel at the northwest side of the location that needs to be repaired. Arrow points to 4.5 ft. shovel.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:307766 | Date: 6/10/2024

## Inspection Photos



**Photo 4.** There are other erosion channels along the cut slope that have not been repaired. The yellow arrow points to Houndstongue noxious weed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:307766 | Date: 6/10/2024