

Inspection Photos

API: 071-06819

Operator: WAPITI OPERATING LLC

Inspection Date: 6/10/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast along the access road. There are noxious weeds that need to be controlled. Red arrow points to Canada thistle.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. Facing northeast along the road. There are noxious weeds that need to be controlled. Red arrow points to Musk thistle.



Inspection Photos



Photo 3. Facing southwest toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-06819 | Date: 6/10/2024

Inspection Photos



Photo 4. The wellhead has a dripping leak.

