

Inspection Photos
Location Name: ROTHE-65N63W/31SESW
Location #: 305178



Photo #1

Rothe 24-31 (123-22602) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 60 yds.



Photo #2

Rothe 24-31, 23-31 Battery site
Abandoned: ALL Equipment Removed
Plugged & Abandoned | PA (2: wells).



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources