

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403821871

Date Received:

06/12/2024

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Caerus

COGCC.inspections@caerusoilandgas.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708903966

Inspection Date: 06/03/2024

FIR Submit Date: 06/04/2024

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335314

Location Name: BENZEL-66S93W Number: 26SENE County: \_\_\_\_\_

Qtrqtr: SENE Sec: 26 Twp: 6S Range: 93W Meridian: 6

Latitude: 39.498490 Longitude: -107.736330

FACILITY - API Number: 05-045-00 Facility ID: 335314

Facility Name: BENZEL-66S93W Number: 26SENE

Qtrqtr: SENE Sec: 26 Twp: 6S Range: 93W Meridian: 6

Latitude: 39.498490 Longitude: -107.736330

CORRECTIVE ACTIONS:

1 CA# 195619

Corrective Action: Comply with CECMC pressure safety device rules

Date: 06/11/2024

Response: CA COMPLETED

Date of Completion: 06/05/2024

Operator Comment: Complied with CECMC pressure safety device rules.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Justin Johnson

Signed:

Title: Compliance

Date: 6/12/2024 6:36:30 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403821872	Untied piping and plugged open drain valve as well as a cap installed on PRV vent.
-----------	--

Total Attach: 1 Files