

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 105-33 Pad

Location ID: 324027



Photo # 500 From entrance to location



Photo # 501 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 105-33 Pad

Location ID: 324027



Photo # 502 Location



Photo # 503 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 105-33 Pad

Location ID: 324027



Jun 11, 2024 at 12:43:02 PM
CO



Jun 11, 2024 at 12:46:15 PM
CO

Photo # 504 Location

Photo # 505 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 105-33 Pad

Location ID: 324027



Photo # 506 Open ended piping on separator/wildlife hazard/available for entry by wildlife



Photo # 507 Open ended piping on separator/wildlife hazard/available for entry by wildlife