

Inspection Photos

Location: Caerus Piceance LLC 697-28C Pad

Location ID: 335510

Date: 6/10/2024



Entrance to location - Photo #02205




Well heads - Photo #02206

Inspection Photos

Location: Caerus Piceance LLC 697-28C Pad

Location ID: 335510

Date: 6/10/2024



Separators - Photo #02211



Wildlife Entry - Photo #02212

Inspection Photos

Location: Caerus Piceance LLC 697-28C Pad

Location ID: 335510

Date: 6/10/2024



Communication - Photo #02220



Meter run - Photo #02223

Inspection Photos

Location: Caerus Piceance LLC 697-28C Pad

Location ID: 335510

Date: 6/10/2024



Tank battery - Photo #02227



Open ended load line - Photo #02234

Inspection Photos

Location: Caerus Piceance LLC 697-28C Pad

Location ID: 335510

Date: 6/10/2024



Open ended load line - Photo #02236



Open ended load line - Photo #02237



Inspection Photos

Location: Caerus Piceance LLC 697-28C Pad

Location ID: 335510

Date: 6/10/2024



Open ended load line - Photo #02240



Debris - Photo #02246

Inspection Photos

Location: Caerus Piceance LLC 697-28C Pad

Location ID: 335510

Date: 6/10/2024



Debris - Photo #02247



Debris - Photo #02251

Inspection Photos

Location: Caerus Piceance LLC 697-28C Pad

Location ID: 335510

Date: 6/10/2024



Debris - Photo #02252



Debris - Photo #02257

Inspection Photos

Location: Caerus Piceance LLC 697-28C Pad

Location ID: 335510

Date: 6/10/2024



Jun 10, 2024 at 11:41:38 AM
+39.491855,-108.229452 ±4.73m
De Beque

Northwest corner of location - Photo #02260



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources