

Inspection Photos

Location Name: ROTHE-65N63W/31SWSW

Location #: 306070



Photo #1

Rothe CSW-31 (123-23945) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 150 yds.



Photo #2

Rothe #1, 13-31, CSW-31 Battery site

Abandoned: ALL Equipment Removed

Plugged & Abandoned | PA (3: wells).



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources