

Inspection Photos

06/4/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 482958

Inspection Doc: 696205867

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 482958



Photo 1: Photo shows cellars and riser equipment have been installed on Location. Fencing, covers, and other BMPs to allow for wildlife egress from the cellars have not been installed, resulting in wildlife entrapment and mortality within multiple cellars.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 482958



Photo 2: Photo example showing wildlife entrapment and mortality observed in the open cellars.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 482958



Photo 3: Photo example showing riser equipment leaking fluids; several leaking risers observed on Location.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 482958



Photo 4: Photo shows work to address the stormwater and stabilization issues along the access road has been performed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources