

# Final Reclamation and Stormwater Inspection

Date: 6/10/24

Operator: Noble Energy Inc - 100322

Location ID: 309878

Inspection Document #: 713900677

Weld County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Sledge C 9-28  
Location ID: 309878



**Photo 1.** The photo was taken at the entrance to the well location facing North. The photo illustrates the historic access road leading up to the entrance to the well location.

**Photo 2.** The photo was taken at the entrance to the well location facing West. The photo illustrates the well and entrance.

Inspection Photos  
Location Name: Sledge C 9-28  
Location ID: 309878



**Photo 3.** The photo was taken at the well location facing North. The photo illustrates the well location is dominated by Cheatgrass with some other grass species and Yellow salsify.

**Photo 4.** The photo was taken at the well location facing East. Refer to the comment for photo 3.

Inspection Photos  
Location Name: Sledge C 9-28  
Location ID: 309878



**Photo 5.** The photo was taken at the well location facing South. Refer to the comment for photo 3.

**Photo 6.** The photo was taken at the well location facing West. Refer to the comment for photo 3.

Inspection Photos  
Location Name: Sledge C 9-28  
Location ID: 309878



**Photo 7.** The photo was taken at the tank battery location facing Northeast. The photo illustrates the tank battery location is dominated by annual weeds including Field bindweed and hay bales stored on location.



**Photo 8.** The photo was taken at the tank battery location facing South. The photo illustrates broken hay bale debris on the location as well as a dominance of annual weeds.

Inspection Photos  
Location Name: Sledge C 9-28  
Location ID: 309878



**Photo 9.** The reference photo was taken South of the well location facing South.