

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Gardner Federal/28-1 (PC-28)

Location ID: 311692

Date: 6/6/2024



Location Entrance – Photo #01644



Wellheads – Photo #01645

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Gardner Federal/28-1 (PC-28)

Location ID: 311692

Date: 6/6/2024



Separators – Photo #01646



Tank Battery – Photo #01650



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Gardner Federal/28-1 (PC-28)

Location ID: 311692

Date: 6/6/2024



ECD – Photo #01647



Gas Meter/Pig Station – Photo #01653



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Gardner Federal/28-1 (PC-28)

Location ID: 311692

Date: 6/6/2024



Insufficient Erosion Control onto Location – Photo #01648



Insufficient Erosion Control onto Location – Photo #01649