

Inspection Photos
Location Name: Lebsock 5-27
API Number: 125-07498



1. Lease sign at well location.



2. View of wellhead.



Inspection Photos
Location Name: Lebsock 5-27
API Number: 125-07498



3. Debris inside well fencing.



4. Power and control panel laying on ground.

Inspection Photos
Location Name: Lebsock 5-27
API Number: 125-07498



5. Stained soil inside well fencing.



6. Well location overview.

Inspection Photos
Location Name: Lebsock 5-27
API Number: 125-07498



7. Remote gas meter shed.



8. Gas meter inside meter shed.

