

**Inspection Photos**  
**Jordan 34-3 Tank Battery**  
**Spill ID 484635/Rem 29080**



**Photo 1 – Open excavation**



**Photo 2 – Open excavation; downed fencing.**

**Inspection Photos**  
**Jordan 34-3 Tank Battery**  
**Spill ID 484635/Rem 29080**



ECMC Environmental Inspection  
40.00503, -104.6542, 1542.0m, 38°  
05/23/2024 09:35:56 AM

**Photo 3 – Open excavation**



ECMC Environmental Inspection  
40.00502, -104.65429, 1538.2m, 321°  
05/23/2024 09:36:33 AM

**Photo 4 – Open excavation; sagging fencing.**

**Inspection Photos**  
**Jordan 34-3 Tank Battery**  
**Spill ID 484635/Rem 29080**



**Photo 5 – Open excavation**



**Photo 6 – Open excavation; downed fencing.**



**Inspection Photos**  
**Jordan 34-3 Tank Battery**  
**Spill ID 484635/Rem 29080**



**Photo 7 – Clean soil stockpile. Downed fencing.**



**Photo 8 – Clean soil stockpile**

**Inspection Photos**  
**Jordan 34-3 Tank Battery**  
**Spill ID 484635/Rem 29080**



**Photo 9 – Clean soil stockpile**



**Photo 10 - Small soil stockpile; unmarked with no BMPs**

Inspection Photos  
Jordan 34-3 Tank Battery  
Spill ID 484635/Rem 29080



**Photo 11 - Small soil stockpile; unmarked with no BMPs (foreground). Large clean soil stockpile (background).**



**Photo 12 - Small soil stockpile; unmarked with no BMPs**



Inspection Photos  
Jordan 34-3 Tank Battery  
Spill ID 484635/Rem 29080



Photo 13 – Open excavation



Photo 14 - Small soil stockpile; unmarked with no BMPs

Inspection Photos  
Jordan 34-3 Tank Battery  
Spill ID 484635/Rem 29080



Photo 15 – Contaminated soil stockpile.



Photo 16 – Contaminated soil stockpile.

**Inspection Photos**  
**Jordan 34-3 Tank Battery**  
**Spill ID 484635/Rem 29080**



**Photo 17 – Contaminated soil stockpile.**



**Photo 18 – Contaminated soil stockpile.**

Inspection Photos  
Jordan 34-3 Tank Battery  
Spill ID 484635/Rem 29080



**Photo 19 – Small unmarked soil stockpile with no BMPs. Downed fencing.**



**Photo 20 – Open excavation; downed fencing.**