

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



Jun 10, 2024 at 1:50:16 PM
CO



Jun 10, 2024 at 2:23:18 PM
CO

TEP Rocky Mountain LLC

970-285-9377

RWF 11-5 PAD

COC none

API

RWF 11-5	05-045-12734
RWF 12-5	05-045-12735
RWF 21-5	05-045-12726
RWF 22-5	05-045-12731
RWF 311-5	05-045-12728
RWF 312-5	05-045-12302
RWF 321-5	05-045-12301
RWF 322-5	05-045-12733
RWF 411-5	05-045-12727
RWF 412-5	05-045-12730
RWF 421-5	05-045-12723
RWF 422-5	05-045-12736
RWF 511-5	05-045-12724
RWF 512-5	05-045-12729
RWF 521-5	05-045-12725
RWF 522-5	05-045-12732

SE NWSEC 5/T7A/R94W

GARFIELD COUNTY, CO

EMS 911

ACCESS FROM: CR.301

Photo # 260 From entrance to location

Photo # 261 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



Photo # 262 Location



Photo # 263 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



Photo # 264 Location



Photo # 265 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



Photo # 266 Location



Photo # 267 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



Photo # 268 Stained soils near chemical drum



Photo # 269 Stained soils near chemical drum

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



Photo # 270 Stained soils



Photo # 271 Stained soils

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



Photo # 272 Stained soils



Photo # 273 Stained soils

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



Photo # 274 Stained soils



Photo # 275

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



Photo # 276 Stored trailer & misc




Photo # 277 Stored equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



Jun 10, 2024 at 1:56:32 PM
CO



Jun 10, 2024 at 1:56:48 PM
CO

Photo # 278 Stored trailer & equipment

Photo # 279 Stored trailer & equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



Jun 10, 2024 at 2:08:57 PM
CO



Jun 10, 2024 at 2:34:18 PM
CO

Photo # 280 Stored vehicles & trailers in the interim area

Photo # 281 Stored vehicles & trailers in the interim area

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



Photo # 282 Stored trailers & misc equipment



Photo # 283 Stored vehicle, trailer & misc equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



Photo # 284 Stored vehicles, trailer & misc equipment



Photo # 285 Stored equipment & trailers

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



Photo # 286 Stored vehicles & misc



Photo # 287 Stored truck & misc

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



Photo # 288 Unmarked deadman



Photo # 289 Same unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



Photo # 290 Unmarked dead



Photo # 291 Same unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



Photo # 292 Unmarked deadman



Photo # 293 Same unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



Photo # 294 Unmarked deadman



Photo # 295 Same unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



Photo # 296 Unmarked deadman



Photo # 297 Same unmarked deadman

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



**Photo # 298 Barbed wire fencing needs maintenance
/wildlife hazard (NW corner of location near separators)**



**Photo # 299 Barbed wire fencing needs maintenance
/wildlife hazard (NW corner of location near separators)**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



**Photo # 300 Barbed wire fencing needs maintenance
/wildlife hazard (NW corner of location near separators)**



**Photo # 301 Barbed wire fencing needs maintenance
/wildlife hazard (NW corner of location near separators)**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



**Photo # 302 Barbed wire fencing needs maintenance
/wildlife hazard (NW corner of location near separators)**



**Photo # 303 Barbed wire fencing needs maintenance
/wildlife hazard (NW corner of location near separators)**

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC STUBBS RWF 11-5 Pad

Location ID: 334713



**Photo # 304 Barbed wire fencing needs maintenance
/wildlife hazard (NW corner of location near separators)**



**Photo # 305 Barbed wire fencing needs maintenance
/wildlife hazard (NW corner of location near separators)**