

Inspection Photos

Location Name: Megan State H16-30D Pad

Location ID: 327755



Photo 1: Wellhead Sign



Photo 2: Wellhead



Inspection Photos
Location Name: Megan State H16-30D Pad
Location ID: 327755



Photo 3: Temp tank removed



Photo 4: Unused equipment

Inspection Photos

Location Name: Megan State H16-30D Pad

Location ID: 327755



Photo 5: Unused equipment (Risers, steps)



Photo 6: Unused equipment, No LOTO

Inspection Photos
Location Name: Megan State H16-30D Pad
Location ID: 327755



Photo 7: Unused equipment, No LOTO




Photo 8: Unused equipment, No LOTO

Inspection Photos
Location Name: Megan State H16-30D Pad
Location ID: 327755



Photo 9: Unused equipment, No LOTO



Photo 10: Unused equipment, No LOTO

Inspection Photos

Location Name: Megan State H16-30D Pad

Location ID: 327755



Photo 11: Unused equipment, No LOTO



Photo 12: Unused equipment, No LOTO

Inspection Photos
Location Name: Megan State H16-30D Pad
Location ID: 327755



Photo 13: Debris removed



Photo 14: Debris