

Inspection Photos
Location Name: HSR-Stroh 11-35
Location ID: 326834



Production facility



Wellhead

Inspection Photos
Location Name: HSR-Stroh 11-35
Location ID: 326834



Berm on 6/5/2024



Berm on 6/14/2024

Inspection Photos
Location Name: HSR-Stroh 11-35
Location ID: 326834



Berm on 6/5/2024



Berm on 6/14/2024