

Inspection Photos
Location Name: State Antelope B-2 PAD
Location ID: 159738



Photo 1 – MT 45 at North Gas Lift Injection Meter House STILL Missing Label

Photo 2 – MT 154 at South Gas Lift Injection Meter House STILL Missing Label

Inspection Photos
Location Name: State Antelope B-2 PAD
Location ID: 159738



Energy and Carbon Management Commission
40.43235, -104.29883, 4588 1ft
06/12/2024 11:46:02



Energy and Carbon Management Commission
40.43346, -104.29948, 4598 8ft
06/12/2024 11:46:44

Photo 3 – Wellheads

Photo 4 – Location Sign

Inspection Photos
 Location Name: State Antelope B-2 PAD
 Location ID: 159738



Photo 5 – Maintenance Tank

Photo 6 – Sign at Entrance