

Inspection Photos

June 12th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 333954

Inspection Document #: 714000826

La Plata County, CO

Township: NWNE 33 34N 10W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Argenta 34-10 32-1
Location ID: 333954



6/12/24
+37.152242,-107.935261
97° E



6/12/24
+37.152336,-107.934935
69° NE

Photo 1. View of the well pad taken from the access road facing center.

Inspection Photos

Location Name: Argenta 34-10 32-1

Location ID: 333954



Photo 2. View of stained soils at the pump jack stand and muffler.

Inspection Photos
Location Name: Argenta 34-10 32-1
Location ID: 333954



Photo 3. View of stained soils at well head.



Inspection Photos

Location Name: Argenta 34-10 32-1

Location ID: 333954



Photo 4. View of unused oil and gas piping and metals panels on location.

Inspection Photos

Location Name: Argenta 34-10 32-1

Location ID: 333954



Photo 5. View of round river rock check dam storm water BMP on location on the northern edge of the disturbance. BMP does not appear affective/adequate as gully erosion is persisting down hill.