

Inspection Photos

June 12th, 2024

Operator: Enduring Resources LLC - 10663

Location ID: 326631

Inspection Document #: 714000834

La Plata County, CO

Township: NENW 5 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: La Posta 5-1
Location ID: 326631



Photo 1. View of the well disturbance taken from the access point facing center.



Inspection Photos
Location Name: La Posta 5-1
Location ID: 326631



Photo 2. Rutting/Stormwater corrective action identified in the previous inspection doc #714000532 has been addressed/resolved.

Inspection Photos
Location Name: La Posta 5-1
Location ID: 326631



Photo 3. Unused oil and gas equipment corrective action identified in the previous inspection doc #714000532 has been addressed/resolved.

Inspection Photos
Location Name: La Posta 5-1
Location ID: 326631



Photo 4. Oily substance and impacted soils observed at the generator in the northeast corner of the disturbance.