

Final Reclamation and Stormwater Inspection

Date: 6/10/24

Operator: Noble Energy Inc - 100322

Location ID: 309877

Inspection Document #: 713900687

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Sledge C 9-29
Location ID: 309877



Photo 1. The photo was taken at the tank battery location facing South. The photo illustrates the tank battery remains active for another well.



Photo 2. The photo was taken West of the well location facing East. The photo illustrates the well location appears to have minimal alfalfa growth however the field has been recently cut.

Inspection Photos
Location Name: Sledge C 9-29
Location ID: 309877



Photo 3. The photo was taken East of the well location facing West. Refer to the comment for photo 2.

Photo 4. The reference photo was taken South of the well location in the same alfalfa field facing South. The photo illustrates the field has been cut recently.