

Inspection Photos


Location: Laramie Energy LLC Laramie Land & Cattle CO. 36-10 Pad

Location ID: 334516

Date: 6/11/2024



Entrance to location - Photo #02368



Location - Photo #02379

Inspection Photos

Location: Laramie Energy LLC Laramie Land & Cattle CO. 36-10 Pad

Location ID: 334516

Date: 6/11/2024



Well heads - Photo #02369



Separators - Photo #02370

Inspection Photos

Location: Laramie Energy LLC Laramie Land & Cattle CO. 36-10 Pad

Location ID: 334516

Date: 6/11/2024



Separators - Photo #02371



Separators - Photo #02376

Inspection Photos

Location: Laramie Energy LLC Laramie Land & Cattle CO. 36-10 Pad

Location ID: 334516

Date: 6/11/2024



Separators - Photo #02377



Tank battery - Photo #02378

Inspection Photos


Location: Laramie Energy LLC Laramie Land & Cattle CO. 36-10 Pad

Location ID: 334516

Date: 6/11/2024



Open entry to wildlife - Photo #02387



Open entry to wildlife - Photo #02388

Inspection Photos

Location: Laramie Energy LLC Laramie Land & Cattle CO. 36-10 Pad

Location ID: 334516

Date: 6/11/2024



Pig launcher - Photo #02390



Northeast corner of location - Photo #02392