

Inspection Photos


Location: Laramie Energy LLC My Way Ranch 18-1 Pad

Location ID: 334412

Date: 6/11/2024



Entrance to location - Photo #02407



Location - Photo #02417

Inspection Photos

Location: Laramie Energy LLC My Way Ranch 18-1 Pad

Location ID: 334412

Date: 6/11/2024



Well heads - Photo #02410



Separators - Photo #02412

Inspection Photos

Location: Laramie Energy LLC My Way Ranch 18-1 Pad

Location ID: 334412

Date: 6/11/2024



Tank battery - Photo #02416



Pig launcher - Photo #02424

Inspection Photos

Location: Laramie Energy LLC My Way Ranch 18-1 Pad

Location ID: 334412

Date: 6/11/2024



Southwest corner of location - Photo #02428

